Active Errata List

- SPI SSDIS Does Not Work
- Baud Rate Generator Idle Mode
- During UART Reception, Clearing REN May Generate Unexpected IT
- Double IT on External Falling Edge on INT1 or INT2 in X2 Mode

Errata History

Lot Number	Errata List
All date codes, starting May 2002	1, 2, 3, 4

Errata Descriptions

1. SPI SSDIS Does Not Work

The SSDIS bit in SPCON register does not work; therefore the \overline{SS} pin cannot be used as a general-purpose I/O when the SPI is used.

Workaround

None.

2. BRG Idle Mode

The BRG clock is stopped in Idle and Pseudo Idle modes.

Workaround

None. When using the BRG, use the standard conversion, the A/D resolution is nearly as good as in pseudo Idle mode.

3. During UART Reception, Clearing REN May Generate Unexpected IT

During UART reception, if the REN bit is clear between a start bit detection and the end of reception, the UART will not discard the data (RI is set).

Workaround

Test REN at the beginning of Interrupt routine just after CLR RI, and run the interrupt routine code only if REN is set.

4. Double IT on External Falling Edge on INT1 or INT2 in X2 Mode

When the CPU is in X2 mode and Timer1 or Timer0 in X1 mode (CKCON = 0x7F), IEx flag is not cleared by hardware after servicing the interrupt. In this case, the CPU executes the ISR a second time.

Workaround

The workaround is to clear IEx bit in the interrupt subroutine.

INT1_ISR: ; Interrupt subroutine

CLR IE1

.....



80C51 Microcontrollers

AT83C5111 AT87C5111 AT83C5112 AT87C5112 AT80C5112

Errata Sheet





Atmel Headquarters

Corporate Headquarters

2325 Orchard Parkway San Jose, CA 95131 TEL 1(408) 441-0311 FAX 1(408) 487-2600

Europe

Atmel Sarl Route des Arsenaux 41 Case Postale 80 CH-1705 Fribourg Switzerland TEL (41) 26-426-5555 FAX (41) 26-426-5500

Asia

Room 1219 Chinachem Golden Plaza 77 Mody Road Tsimhatsui East Kowloon Hong Kong TEL (852) 2721-9778 FAX (852) 2722-1369

Japan

9F, Tonetsu Shinkawa Bldg. 1-24-8 Shinkawa Chuo-ku, Tokyo 104-0033 Japan TEL (81) 3-3523-3551 FAX (81) 3-3523-7581

Atmel Operations

Memory

2325 Orchard Parkway San Jose, CA 95131 TEL 1(408) 441-0311 FAX 1(408) 436-4314

Microcontrollers

2325 Orchard Parkway San Jose, CA 95131 TEL 1(408) 441-0311 FAX 1(408) 436-4314

La Chantrerie BP 70602 44306 Nantes Cedex 3, France TEL (33) 2-40-18-18-18 FAX (33) 2-40-18-19-60

ASIC/ASSP/Smart Cards

Zone Industrielle 13106 Rousset Cedex, France TEL (33) 4-42-53-60-00 FAX (33) 4-42-53-60-01

1150 East Cheyenne Mtn. Blvd. Colorado Springs, CO 80906 TEL 1(719) 576-3300 FAX 1(719) 540-1759

Scottish Enterprise Technology Park Maxwell Building East Kilbride G75 0QR, Scotland TEL (44) 1355-803-000 FAX (44) 1355-242-743

RF/Automotive

Theresienstrasse 2 Postfach 3535 74025 Heilbronn, Germany TEL (49) 71-31-67-0 FAX (49) 71-31-67-2340

1150 East Cheyenne Mtn. Blvd. Colorado Springs, CO 80906 TEL 1(719) 576-3300 FAX 1(719) 540-1759

Biometrics/Imaging/Hi-Rel MPU/ High Speed Converters/RF Datacom

Avenue de Rochepleine BP 123 38521 Saint-Egreve Cedex, France TEL (33) 4-76-58-30-00 FAX (33) 4-76-58-34-80

e-mail

literature@atmel.com

Web Site http://www.atmel.com

© Atmel Corporation 2002.

Atmel Corporation makes no warranty for the use of its products, other than those expressly contained in the Company's standard warranty which is detailed in Atmel's Terms and Conditions located on the Company's web site. The Company assumes no responsibility for any errors which may appear in this document, reserves the right to change devices or specifications detailed herein at any time without notice, and does not make any commitment to update the information contained herein. No licenses to patents or other intellectual property of Atmel are granted by the Company in connection with the sale of Atmel products, expressly or by implication. Atmel's products are not authorized for use as critical components in life support devices or systems.

ATMEL[®] is a registered trademark of Atmel.

Other terms and product names may be the trademarks of others.

Printed on recycled paper.