3-phase motor driver BA6871BS

The BA6871BS is a 3-phase, full-wave, pseudo-linear motor driver suited for VCR capstan motors. The IC has a torque ripple cancellation circuit to reduce wow and flutter, and an output transistor saturation prevention circuit that provides superb motor control over a wide range of current. The built-in motor power series regulator allows applications with low power consumption.

Applications3-phase VCR capstan motors

Features

- 1) 3-phase, full-wave, pseudo-linear driver system.
- 2) High performance torque ripple cancellation circuit.
- 3) Reversal braking by detecting the motor direction.
- 4) Saturation prevention circuit for high- and low-side output transistors.
- 5) Motor power supply series regulators.
- Built-in circuit for output-to-GND short-circuit detection.
- 7) Two FG amplifiers.
- 8) Available in a SDIP 32-pin power shrink package.

Parameter	Symbol	Limits	Unit
Applied voltage	Vcc1	7	V
Applied voltage	Vм	36	V
Applied voltage	Vcc2	36	V
Applied voltage	AMP-Vcc	14	V
Power dissipation	Pd	1700*1	mW
Operating temperature	Topr	-20~+75	Ĉ
Storage temperature	Tstg	-40~+150	C
Allowable output current	lopeak	1.5*²	А
Input voltage	VIN	-0.2~+Vcc	V

•Absolute maximum ratings (Ta = 25° C)

*1 Reduced by 13.6 mW for each increase in Ta of 1°C over 25°C.

*2 Should not exceed Pd or ASO values.

•Recommended operating conditions (Ta = 25° C)

Parameter	Symbol	Min.	Тур.	Max.	Unit
Operating power supply voltage	Vcc1	4	5	6	V
Operating power supply voltage	Vcc2	3	—	32	V
Operating power supply voltage	Vм	3	12	32	V
Operating power supply voltage	AMP-Vcc	4	12	13	V

O Not designed for radiation resistance.

Block diagram



Pin descriptions

Pin No.	Pin name	Function	No. of I/O circuits
1	A2	Motor output	Fig.1
2	Vм	Motor power supply	Fig.1
3	A1	Motor output	Fig.1
4	REG	Series regulator sink output	Fig.6
5	PCR	Series regulator phase compensation	Fig.6
6	Vcc2	Signal power supply 2	Fig.1
7	GND	Signal ground	-
8	PCV	Phase compensation for preventing driver high-side saturation	-
9	PCI	Phase compensation for preventing driver low-side saturation	-
10	ECR	Torque control reference input	Fig.4
11	EC	Torque control signal input	Fig.4
12	TL	Torque limit	Fig.5
13	CS	Current sensing input	Fig.5
14	Vcc1	Signal power supply 1	-
15	PCH	Hall amplifier AGC phase compensation	-
16	SUB-GND	SUB ground pin, also serves as a radiation FIN	-
17	H1 ⁺	Hall signal input	Fig.2
18	H1 ⁻	Hall signal input	Fig.2
19	H2+	Hall signal input	Fig.2
20	H2-	Hall signal input	Fig.2
21	H3+	Hall signal input	Fig.2
22	H3 ⁻	Hall signal input	Fig.2
23	AMP-GND	FG amplifier ground pin	-
24	IN1	FG amplifier 1 input	Fig.7
25	OUT1	FG amplifier 1 output	Fig.7
26	IN2	FG amplifier 2 input	Fig.7
27	OUT2	FG amplifier 2 output	Fig.7
28	AMP-Vcc	FG amplifier power supply	-
29	ED / S	Forward / stop / reverse mode switching input	Fig.3
30	A3	Motor output	Fig.1
31	ATC	Driver ground	Fig.1
32	SUB-GND	SUB ground pin, also serves as a radiation FIN	-

Input/output circuits

(1) Driver output













Fig. 4

(5) Torque limit and current sensing



Fig. 5

(6) Series regulator





(7) Amplifier I/O



Fig. 7

BA6871BS

Parameter	Symbol	Min.	Тур.	Max.	Unit	Conditions
Supply current	lcc	-	10	16	mA	$E_{C}=E_{CR}$, ED / S=M, Input=(L, L, H)
Torque control voltage	Ec	1	-	4	V	Ec input range
Torque control voltage offset	ECofs	-110	-	+110	mV	
Torque control dead zone	Ecdz	50	-	170	mV	
Output idle voltage	ECidle	_	-	5	mV	Within the dead zone, ED/S=L
Output idle current	Ecidle	_	-	2	mA	ED/S=M
Torque control I/O gain	Gio	0.26	0.32	0.38	_	Ec=2.2→2.1 V, input=(L, L, H)
Forward ON voltage	ED / F	_	-	0.9	V	
Stop ON voltage	ED / S	1.3	-	3.0	V	
Reverse ON voltage	ED / R	3.5	-	-	V	
Hall input voltage	VHDC	1.2	-	3.2	V	
Hall input conversion offset	HEofs	-10	-	+10	mV	
Hall input conversion offset differential	ΔHEofs	-15	-	+15	mV	
TL-CS offset	TL-CSofs	10	35	65	mV	
Ripple cancellation ratio	VRCC	4.0	6.3	8.6	%	Input=(L, L, H)→(L, M, H)
Output high level voltage	Vон	0.9	1.3	1.70	V	Io=0.8A
Output low level voltage	Vol	0.95	1.3	1.65	V	Io=0.8A
Series regulator operating voltage	VREG	Vм —0.70	Vм —0.95	Vм −1.2	v	Ec=1.5V, VM=Vcc2=15V
Series regulator current capacity	IREG	17	30	-	mA	Ec=0V, Vreg=2V
Short-circuit detection operating voltage	Voff	60	90	120	mV	
〈FG amplifier〉						
Circuit current	AMP-lcc	_	1.1	3.0	mA	
Bias voltage	VBI	5.3	6.2	6.8	V	
Input current (AMP1)	lin	_	0.5	5.0	μA	VIN=1.0V
Output high level voltage (AMP1)	Voha	_	1.0	1.5	V	Io=-0.5mA
Output low level voltage (AMP1)	Vola	_	1.0	1.5	v	Io=+0.5mA
Open loop gain 1	Gv1	50	-	-	dB	f=1kHz
Open loop gain 2	Gv2	28	_	_	dB	f=20kHz

Circuit operation

(1) Pseudo-linear output and torque ripple cancellation The IC generates a trapezoidal (pseudo-linear) output current, whose waveform phase is 30 degrees ahead of that of the Hall input voltage (Fig. 8).



The trapezoidal waveform of output current would create intermittence in the magnetic field generated by the 3-phase motor, and would result in an irregular rotation of the motor. To prevent this, the output waveform is obtained by superimposing a triangular wave on the trapezoidal wave (Fig. 9). This process is called torque ripple cancellation.



Fig. 9

(2) Torque control and reversal brake

The output current can be controlled by adjusting the voltage applied to the torque control pins (pins 10 and 11).



Fig. 10

These pins are the inputs to a differential amplifier. A reference voltage between $2.3 \sim 3.0V$ (2.5V recommended) is applied to pin 10.

A brake is applied to the motor as described in the following. When the motor is running, pin 11 is given a negative potential with respect to the reference potential. If the pin 11 potential becomes positive, the IC detects the rise of pin 11 potential above the reference potential and activates the motor direction detecting circuit.

The motor direction detecting circuit sends a signal to the motor direction setting circuit to reverse the motor direction. This causes a braking torque that depends on the pin 11 potential, so that the motor quickly reduces its speed. At the same time, the positive pin 11 potential is shifted to the reference potential, so that the motor stops smoothly.

(3) Output current sensing and torque limitation

Pin 31 is the ground pin for the output stage. To sense the output current, a resistor $(0.5\Omega \text{ recommended})$ is connected between pin 31 and the ground. The output current is sensed by applying the voltage developed across this resistor to pin 13 as a feedback.

The output current can be limited by adjusting the voltage applied to pin 12. The current is limited when pin 12 reaches the same potential as pin 13. The output current ($I_{MAX.}$) under this condition is given by:

$$I_{MAX.} = \frac{V_{12P} - (TL - CS_{ofs})}{R_{31P}}$$

where R_{31P} is the value of the resistor connected between pin 31 and the ground, V_{12P} is the voltage applied to pin 12, and (TL – CS_{ofs}) is the offset between the TL and CS pins.



Fig.11 Output circuit



(4) Motor direction control (pin 29)

The motor mode is:

Forward when the pin 29 voltage is less than 0.9V, Stop when the voltage is between $1.3 \sim 3.0V$, Reverse when the voltage is above 3.5V. In the stop mode, high- and low-side output transistors are turned off, resulting in a high impedance state.

(5) Output transistor saturation prevention circuit This circuit monitors the output voltage and maintain the operation of the output transistors below their saturation levels. Operating the transistors in the linear characteristic range provides good control over a wide range of current and good torque characteristics even during overloading.



Fig.12 Output high level voltage vs. output current (reference curves)



Fig.13 Output low level voltage vs. output current (reference curves)

(6) Series regulator

The BA6871BS has a series regulator output pin. The IC outputs a sink current according to the HIGH level output voltage detected.



As shown in Fig. 14, the regulator circuit reduces the power consumed by the IC by reducing the collector-toemitter (C-E) voltage of the driver transistors.

Nearly all the power dissipated by the IC is dissipated between the collectors and emitters of the output transistors. More power is consumed as the C-E voltage increases and as the output current increases.

The output transistor C-E voltage is equal to the difference between the supply voltage and the voltage applied to the motor. Because the voltage across the motor decreases with decreasing drive current, the C-E voltage must increase if the supply voltage is fixed.

Therefore, to improve the efficiency of the driver and to prevent the power rating of the IC being exceeded, the supply voltage must be varied in response to changes in the output current. The supply voltage is decreased at low current and increased at high current so that no excessive voltage is applied between the transistor collectors and emitters.

(7) Output-to-ground short-circuit detection

The motor output pins of the IC may be short-circuited to the ground by some fault conditions. A short-circuited output can destroy the output transistors because of excessive current, excessive voltage, or both. Even when a short-circuit condition does not completely destroy the device, it can still cause extreme overheating. To prevent this, the BA6871BS contains a short-circuit detection circuit that turns off the motor drive current if the output-toground potential becomes abnormally low.

Application example



Fig.15

Operation notes

The BA6871BS has two thermal shutdown circuits (TSD1 and TSD2) to protect the IC. The typical shutdown temperatures are 175°C for TSD1 and 215°C for TSD 2. When the TSD1 is activated at an elevated chip temperature, the output pins (pins 1, 3, and 30) are set to the open state. TSD1 is functional against excessive power dissipation, output short-circuiting, and other irregularities in the output current, but does not work against overheating caused by high internal currents due to externally caused IC damage or pin-to-pin short-circuiting.

When TSD2 is activated at a higher chip temperature, the high- and low-side output transistors are turned on, and the internal resistance between the motor power supply

pin (pin 2) and the output ground pin (31 pin) drops to less than 3Ω . The motor power supply current (I_M) is then given by

$$I_{M} = \frac{V_{M} \left[V\right]}{R_{M} + R_{31P} + 3 \left[\Omega\right]}$$

where

I_M is the motor supply current

V_M is the motor supply voltage,

 R_M is the motor power supply output resistance,

R_{31P} is the pin-31 resistance.

In your application, make sure to connect between the motor power supply and pin 2 a circuit breaker that operates at currents less than I_{M} .



Electrical characteristic curves



External dimensions (Units: mm)



