# Reversible motor driver **BA6950FS**

Motor driver ICs

The BA6950FS is a reversible-motor driver suited for brush motors. Two logic inputs allow four output modes : forward, reverse, stop (standby), and brake. The rotational speed of motor can be set arbitrarily by changing the voltage applied to the motor with control pins. The IC can also drive a motor at a constant speed by using a built-in current feedback amplifier.

### Applications

VCRs, audio equipment

## Features

- 1) Two logic inputs allow four output modes : forward, reverse, stop (standby), and brake.
- 2) Motor speed variable with voltage control signals.
- 3) Built-in current feedback amplifier allows constant motor speed.
- 4) Control gain can be set arbitrarily by using external resistors.
- 5) Built-in thermal shutdown circuit.

Parameter	Symbol	Limits	Unit	
Applied voltage	Vcc	8	v	
Applied voltage	VB	18	v	
Power dissipation	Pd	800*1	mW	
Operating temperature	Topr	-20~75	°	
Storage temperature	Tstg	-55~150	ۍ ا	
Output current	ίουτ	400*2	mA	

#### Absolute maximum ratings (Ta=25°C)

\*1 Mounted on a glass epoxy PCB (90 X 50 X 1.6 mm).

Reduce power by 6.4 mW for each degree above 25°C.

\*2 Should not exceed Pd- or ASO-value.

#### Recommended operating conditions (Ta=25°C)

Parameter	rameter Symbol Range		Unit
Recommended power supply voltage	Vcc	3~6	v
	VB	3~16	v
	Vctl	0~(Vcc-1.8V)	V

ROHM

471

## **Motor driver ICs**

## BA6950FS

ļ

## Block diagram



## Pin description

Pin No.	Pin name	Function		
1	GND	GND		
2	VCTL	Control signal input pin		
3	RC	Resistor connection pin for control gain setting		
4	PCT	Capacitor connection pin for control phase compensation		
5	RIN	Logic input pin		
6	VB	Driver power supply pin		
7	M1	Motor output pin		
8	ATC	Resistor connection pin for output current detection		
9	M2	Motor output pin		
10	Fіn	Logic input pin		
11	PC	Capacitor connection pin for current feedback phase compensation		
12	Vcc	Signal power supply pin		
13	CS1	Resistor connection pin for CSAMP gain setting		
14	CS2	Resistor connection pin for CSAMP gain setting		
15	RT2	Resistor connection pin for control gain setting		
16	RT1	Resistor connection pin for control gain setting		

472

# ROHM



## **BA6950FS**







ROHM

473

## ●Electrical characteristics (unless otherwise noted, Ta=25℃, Vcc=4.8V, VB=4.8V)

Parameter	Symbol	Min.	Тур.	Max.	Unit	Conditions
Circuit current 1	lcc1	_	4.0	6.0	mA	$(R_{IN}, F_{IN}) = (L, H) \text{ or } (H, L), V_{CTL} = 0V$
Circuit current 2	Icc2	_	0.7	1.5	mA	$(R_{IN}, F_{IN}) = (L, L), V_{CTL} = 0V$
Circuit current 3	Boff	-	0	1.0	μA	IB when V <sub>CC</sub> = 0 V
HIGH level R/F voltage	Vr/FH	2.0			v	
LOW level R/F voltage	Vrv≉l	_	_	0.8	v	
HIGH level input current	lrv∉ n	_	80	135	μA	RIN=2V, FIN=2V
CTL amplifier offset	VCTL of6	-5.0	_	+5.0	mV	(VcrL- RC) when VcrL = 0 V, 1 V
CTL amplifier gain	VCTL Ga	40	46	52	μΑ/V	$\Delta I_{BT1}$ /1 when VctL = 2 V, 1 V
CTL output mirror ratio 1	ICTLR1	0.85	1	1.15	ratio	latt /lac when lac = 20 $\mu$ A
CTL output mirror ratio 2	ICTLR2	0.90	1	1.10	ratio	IRT1 /IRC when IRC = 200 $\mu$ A
CS amplifier offset	CS ofs	-5.0	_	+5.0	mV	(CS1 - CS2) when CS1 = 0 V, 0.1 V
CS output mirror ratio 1	ICSR1	0.85	1	1.15	ratio	IBT2/Ics2when Ics2= 20 µ A
CS output mirror ratio 2	ICSR2	0.90	1	1.10	ratio	IRT2/ICS2when ICS2= 200 µ A
HIGH level output voltage	Vн	2.0	4.6	_	V	M1, M2 voltage when VorL = 0.2 V
Low-side output saturation voltage	Vol	_	0.07	0.2	V	RT1 = Vcc when Io = 50mA
High-side output saturation voltage	Vон	_	0.09	0.3	V	RT1 = Vcc when Io = 50mA

O Not designed for radiation resistance

#### Circuit operation

#### (1) Input section (FIN, RIN)

Control signals are input from these pins. Current flows from M2 to M1 (forward mode) when FiN is HIGH and RIN is LOW, and from M1 to M2 (reverse mode) when RIN is HIGH and FIN is LOW. Putting FiN and RIN both HIGH results in the brake mode in which the highside output transistor is turned off to shut down the motor driving current and the low-side output transistor is turned ON to absorb the counter-electromotive force of the motor, so that a brake is put on the motor. When FIN and RIN are both LOW, both M1 and M2 are left open and the motor stops.

Input/output truth table

Fin	Rin	M1	M2	Mode
н	L	L.	н	Forward
L	Н	н	L	Reverse
н	н	L L		Brake
L	L	OP	Standby	

(2) Output section (M1, M2)

Two logic inputs control the motor by changing the status of bridge-configured transistors.

#### (3) HIGH level output voltage

Values of current, voltage, and HIGH level output voltage can be set as follows by using external resistors (refer to the application circuit of Fig. 4).

• 116 pin (Iвт1)	
116 pin (Iвт)=V2 pin/R1	•••①
• 115 pin (Iatz)	
l15 pin (lвт₂)=l8 pin×R5/R4	· · · ②
• V16 pin (Vat1)	
V16 pin=R3 $\times$ (l16 pin+l15 pin)+R2 $\times$	(I16 pin
	•••③
V7, 9 pin (M1, M2 voltage; high-side voltage)	je)
V7, 9 pin=4 × V16 pin (Typ.)	· · · ④

(4) Current feedback amplifier

The pin-8 current is increased when the motor rotational speed is reduced by loading, and the current feedback amplifier increases the pin-15 current according to equation ②. Because the pin-16 voltage then increases according to equation ③, the HIGH level output voltage also increases according to equation ④. In this way, the rotational speed is kept constant by increasing the voltage applied to the motor.

## rohm

## Motor driver ICs

## BA6950FS



#### Operation notes

(1) Thermal shutdown circuit

The thermal shutdown (TSD) circuit turns off all driver outputs when the IC junction temperature rises above  $175^{\circ}$ C. The temperature difference between the activation and deactivation settings is about 20°C.

Temperature setting of TSD

	Min.	Тур.	Max.	Unit
TSD activation temperature	150	175	200	ĉ
Hysteresis width	_	20	—	C,

(2) Control logic and control signal input pins

Voltage should never be applied to the control logic input pins (pins 5 and 10) or the control signal input pin (pin 2) when the Vcc voltage is not applied to the IC. Similarly, the voltage on each input pin should not exceed any applied Vcc voltage.

(3) PCB arrangement

When changing the rotational direction of a motor, a

large current of up to a few hundred milliamperes can flow between the motor power supply (pin 6) and RNF (pin 8). Depending on the application, this large output current may flow back to input pins, resulting in output oscillation or other malfunctions. Make sure that your design does not allow a common impedance between the large current output lines and the input section. Suppress the power supply impedance to low levels, otherwise output oscillation may occur.

(4) Package power

The power dissipated by the IC varies widely with the supply voltage and the output current. Give full consideration to the package power dissipation rating when setting the supply voltage and the output current.

(5) The input pins (pins 5 and 10) have temperaturedependent characteristics. Take the temperature effect into consideration when using the IC.

(6) To eliminate motor noise, connect a capacitor between M1 (pin 7) and GND and between M2 (pin 9) and GND.

ROHM





ļ.

#### Notes

- The contents described in this catalogue are correct as of March 1997.
- No unauthorized transmission or reproduction of this book, either in whole or in part, is permitted.
- The contents of this book are subject to change without notice. Always verify before use that the contents are the latest specifications. If, by any chance, a defect should arise in the equipment as a result of use without verification of the specifications, ROHM CO., LTD., can bear no responsibility whatsoever.
- Application circuit diagrams and circuit constants contained in this data book are shown as examples of standard use and operation. When designing for mass production, please pay careful attention to peripheral conditions.
- Any and all data, including, but not limited to application circuit diagrams, information, and various data, described in this catalogue are intended only as illustrations of such devices and not as the specifications for such devices. ROHM CO., LTD., disclaims any warranty that any use of such device shall be free from infringement of any third party's intellectual property rights or other proprietary rights, and further, assumes absolutely no liability in the event of any such infringement, or arising from or connected with or related to the use of such devices.
- Upon the sale of any such devices; other than for the buyer's right to use such devices itself, resell or otherwise dispose of the same; no express or implied right or license to practice or commercially exploit any intellectual property rights or other proprietary rights owned or controlled by ROHM CO., LTD., is granted to any such buyer.
- The products in this manual are manufactured with silicon as the main material.
- The products in this manual are not of radiation resistant design.

The products listed in this catalogue are designed to be used with ordinary electronic equipment or devices (such as audio-visual equipment, office-automation equipment, communications devices, electrical appliances, and electronic toys). Should you intend to use these products with equipment or devices which require an extremely high level of reliability and the malfunction of which would directly endanger human life (such as medical instruments, transportation equipment, aerospace machinery, nuclear-reactor controllers, fuel controllers, or other safety devices) please be sure to consult with our sales representatives in advance.

- Notes when exporting
  - It is essential to obtain export permission when exporting any of the above products when it falls under the category of strategic material (or labor) as determined by foreign exchange or foreign trade control laws.
  - Please be sure to consult with our sales representatives to ascertain whether any product is classified as a strategic material.